

















	LAD-34 	 < 4 mm ²	 > 4 mm ²
LC2D09/D12			
LC2D18/D25			
LC2D32			
	+ LAD-33 		+ LAD-33 




⚠ DANGER

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
 Disconnect all power before servicing equipment.
 Failure to follow these instructions will result in death
 or serious injury.




AC, DC, LC




LADN

AC, DC




LADN

AC, DC






LADT
LADR



LAD8N



LRD●●3



LAD6K
LADN
LADT
LADR

