

PRODUCT-DETAILS

3HAC067446-003

Control cable signal,15m

"No longer for sale" replaced by 3HAC084767-



General Information	
Product ID	3HAC067446-003
ABB Type Designation	-
Catalog Description	Control cable signal,15m

Ordering	
Replacement Product ID (NEW)	3HAC084767-003
Country of Origin	China (CN)
Invoice Description	Control cable signal,15m
Minimum Order Quantity	1 piece
Selling Unit of Measure	piece
Order Multiple	1 piece
Quote Only	No
Made To Order	No



Classifications

Customs Tariff Number	85444290
Part Type	New
WEEE Category	Product Not in WEEE Scope

Dimensions

Product Net Weight	1.34 kg
Gross Weight	1.34 kg

Additional Information

Frame Size	Undefined
Product Name	Control cable signal,15m
ABB Type Designation	-

Where Used (as a spare part for "Products")

Identifier	Description	Quantity	Unit Of Measure
9AAF602119	No Description Available	1	piece
9AAF603567	No Description Available	1	piece

Product specific part data

Product

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

Categories

Robotics → Controllers → OmniCore → OmniCore Compact Line → OmniCore C30
Robotics → Controllers → OmniCore → OmniCore Compact Line → OmniCore C90

Category

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

Robot Design Year

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

Robot Part Location

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

Robotics Part Category

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

An error has occurred while processing HtmlTextBox "":
The expression contains undefined function call GetDictionaryItemValue().

