

PRODUCT-DETAILS

# VM7001A

## LV Explosion Proof Motors 460 V (VM7001A)



### General Information

Global Commercial Alias	VM7001A
Product ID	7BVM7001A
ABB Type Designation	.25HP,1725RPM,3PH,60HZ,56C,3410M,XP
Catalog Description	LV Explosion Proof Motors 460 V (VM7001A)

### Ordering

ABB Type Designation	.25HP,1725RPM,3PH,60HZ,56C,3410M,XP
Invoice Description	.25HP,1725RPM,3PH,60HZ,56C,3410M,XPFC,F1
Product Name	LV Explosion Proof Motors
Product Type	Undefined
Made To Order	No
Minimum Order Quantity	1 piece
Order Multiple	1 piece
Selling Unit of Measure	piece
Country of Origin	United States (US)
Customs Tariff Number	85015100
Replaced Product ID	7B34-5336-5724



(OLD)

Stocked At (Warehouses)	China
Medium Description	Frame Size 56C, 3 Phase, XPFC Enclosure, (VM7001A)
Short Description	Frame Size 56C, 3 PH, XPFC,

## Electrical

Electrical Data

### Current

An error has occurred while processing HtmlTextBox ":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":  
The expression contains undefined function call GetListItemValue().

Frequency (f)	60 Hz
Ambient Temperature	40 °C

## Mechanical

Frame Material	Steel
Frame Size	Undefined

## Dimensions

Product Net Depth / Length	16.5 in
Product Net Height	11.375 in
Product Net Width	11.75 in
Product Net Weight	25 lb
Gross Weight	25 lb

## Classifications

Standards	NEMA
UNSPSC	26101112

## Categories

---

**Freq**

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

---

---

**Power**

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

---

---

**Speed**

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

---

---

**Voltage**

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox "":  
The expression contains undefined function call GetListItemValue().

---

Motors and Generators → Motors and Generators for Explosive Atmospheres → Explosion Proof Motors → Inverter Duty Motors

