

# SIEMENS

## SIMATIC

### S7-1200

## CM 1241 firmware update V2.0.3

### Product Information

## Description

The S7-1200 CM 1241 firmware update V2.0.3 provides general robustness improvement in the operational behavior of the communication module CM 1241. The S7-1200 CM 1241 firmware update V2.0.3:

- Fixes compatibility issue V1.0 CPUs (both modules)
- Prevents missing the beginning characters of a response message (CM 1241 RS422/485 module)
- Prevents port lock-up during a receive buffer overflow condition (both modules)

Refer to the SIMATIC S7-1200 System Manual for more information about the S7-1200 product family.

Table 1 Communication modules affected by the CM 1241 firmware update V2.0.3

Communication module	Description	Order number
RS232	CM 1241 RS232	6ES7 241-1AH32-0XB0
RS422/485	CM 1241 RS422/485	6ES7 241-1CH32-0XB0

## Required user action

You can install the firmware update from either the Web server or by making a SIMATIC S7 memory card that contains the firmware update. The S7-1200 System Manual documents both methods.

Siemens AG  
Division Digital Factory  
Postfach 48 48  
90026 NÜRNBERG

CM 1241 firmware update V2.0.3  
A5E33507026-AB, 01/2015